


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 10579	Main Street: RUSH_AV	Cross Street: TUCKASEEGEE_RD	Location: NE
ADA ID: B38B1635B8A1	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 21.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>	
	<b>Remove &amp; Replace Entire Ramp.</b>		<b>N/A</b>	Ramp Length (in)	<b>61.0</b>	<b>N/A</b>
			<b>No</b>	Ramp Width (in)	<b>47.5</b>	<b>N/A</b>
			<b>No</b>	Ramp Slope (%)	<b>9.0</b>	<b>N/A</b>
			<b>Yes</b>	Ramp XSlope (%)	<b>1.2</b>	
			<b>N/A</b>	Flare Type LT	<b>N/A</b>	<b>N/A</b>
			<b>N/A</b>	Flare Slope LT (%)	<b>N/A</b>	<b>N/A</b>
			<b>N/A</b>	Flare Traversable LT?	<b>N/A</b>	<b>N/A</b>
			<b>N/A</b>	Landing Length (in)	<b>0.0</b>	<b>N/A</b>
			<b>N/A</b>	Landing Width (in)	<b>0.0</b>	<b>N/A</b>
			<b>N/A</b>	Landing Slope (%)	<b>0.0</b>	<b>N/A</b>
			<b>N/A</b>	Landing X Slope (%)	<b>0.0</b>	<b>N/A</b>
			<b>N/A</b>	Landing Curb? (Y/N)	<b>N/A</b>	<b>N/A</b>
			<b>N/A</b>	Shared Landing?	<b>N/A</b>	<b>N/A</b>
			<b>N/A</b>	Gutter Ponding?	<b>0.0</b>	<b>N/A</b>
			<b>N/A</b>	Gutter Lip Ht (in)	<b>0.0</b>	<b>N/A</b>
			<b>N/A</b>	Painted X Walk1?	<b>No</b>	
				X Walk 1 Direction	<b>To NW</b>	
				X Walk 1 Width (in)	<b>N/A</b>	
				X Walk 1 Slope (%)	<b>1.5</b>	<b>N/A</b>
				X Walk 1 X Slope (%)	<b>4.5</b>	<b>N/A</b>
			<b>N/A</b>	Ramp inside XWalk1?	<b>N/A</b>	
			<b>N/A</b>	Any Obstructions?	<b>N/A</b>	
				Obstruction Type		
					<b>Yes</b>	<b>Good</b>
					<b>N/A</b>	<b>12.4</b>
Surveyor Notes:						
<b>N/A</b>						
PROW/ADA:						
<b>R304.5.1, R304.2.2</b>						
Total Cost:			<b>\$</b>	<b>1600.00</b>		

Street 1 Name	<b>RUSH AV</b>
Stop Condition-Street 1	<b>StopSign</b>
Street 2 Name	<b>N/A</b>
Stop Condition-Street 2	<b>N/A</b>

