

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

52.0

48.0

13.4

1.1

5.2

3.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 20234 Main Street: SHOPTON RD WEST **Cross Street: WITHERS RD** Location: NW ADA ID: B3BDB3DEB0C8 **Overall Compliance: No** Severity Score: 26.25 Ramp Type: Combination1 Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No

Yes

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Flare Traversable RT?

Data

56.0

48.0

5.6

2.7

51.0

48.0

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name None SHOPTON RD WEST Stop Condition-Street 1 N/A Street 2 Name Stop Condition-Street 2 N/A

Compliance Description Possible Solutions: N/A Remove & Replace Entire Ramp. Yes Yes No N/A Yes Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: N/A R304.5.3, R304.3.2 N/A N/A N/A N/A

Total Cost:



1800.00

N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk2? N/A Painted X Walk1? No N/A To SE N/A X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A 1.9 X Walk 2 Slope (%) N/A X Walk 1 Slope (%) X Walk 1 X Slope (%) 2.9 X Walk 2 X Slope (%) N/A N/A N/A Ramp inside XWalk1? N/A Ramp inside XWalk2? N/A Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 2.1 Curb Slope (%)

