

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.1

0.4

N/A

13.0

Yes

Yes

Yes

24.0

No

6.0

0.4

1.3

N/A

N/A

N/A

N/A

N/A

N/A

Yes

N/A

No

N/A

Good

Intersection ID: 10040584 Main Street: W ARROWOOD RD Cross Street: N/A Location: NW Initial Pass/Fail: Pass **Overall Compliance: No** ADA ID: B3FAE92E3C5E Ramp Type: Perp **Severity Score:** 7.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

N/A

No

N/A

Yes

Yes

Yes

Yes

Yes

N/A

N/A

N/A

N/A

Yes

Yes

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Flare Type RT

Data

71.0

63.0

12.0

No

54.0

63.0

0.9

1.5 No

No No

No

No

0.0

No

To E

N/A

0.6

3.0

N/A

N/A

N/A

No

N/A

Sloped

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?



W ARROWOOD RD Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	Compli	ance	Description
Remove & Replace Entire Ramp.	N/A Ramp		Length (in)
·	Yes	Ramp	Width (in)
	N/A	Flare Type LT Flare Slope LT (%)	
	N/A		
	N/A	Flare	Traversable LT
	Yes	Landi	ng Length (in)
Surveyor Notes:	Yes	Landi	ng Width (in)
N/A	Yes	Landi	ng Slope (%)
	Yes	Landi	ng X Slope (%
	N/A	Landi	ng Curb? (Y/N
	N/A	Share	ed Landing?
PROW/ADA:	Yes	Gutte	er Ponding?
R304.2.3, R305.1.4, R305.2	Yes	Gutte	r Lip Ht (in)
	N/A	Paint	ed X Walk1?
		X Wa	lk 1 Direction
	N/A	X Wa	lk 1 Width (in)
		X Wa	lk 1 Slope (%)
		X Wa	lk 1 X Slope (%
	N/A	Ramp	inside XWalk



Total Cost:



Yes

1850.00

