

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|   |                               |   |                        |
|---|-------------------------------|---|------------------------|
| Intersection ID: N/A                    | Main Street: ORCHID_BRDIGE_RD | Cross Street: N/A                       | Location: N            |
| ADA ID: B4640BDCC607                    | Ramp Type: Perp               | Initial Pass/Fail: Pass                 | Overall Compliance: No |
| Severity Score: 0.25                    |                               |   |                        |
| Codes/Mitigation Info/Possible Solution |                               | Field Measurements/Component Compliance |                        |



Possible Solutions:

**Remove & Replace Entire Ramp.  
Remove & Replace Gutter.**

Surveyor Notes:

**N/A**

PROW/ADA:

**R304.5.3**

Total Cost:

**\$ 2600.00**

| Compliance | Description           | Data   | Compliance | Description                 | Data |
|------------|-----------------------|--------|------------|-----------------------------|------|
| N/A        | Ramp Length (in)      | 99.0   | Yes        | Ramp Slope (%)              | 6.5  |
| Yes        | Ramp Width (in)       | 49.5   | No         | Ramp XSlope (%)             | 4.6  |
| N/A        | Flare Type LT         | Sloped | N/A        | Flare Type RT               | N/A  |
| N/A        | Flare Slope LT (%)    | 9.8    | Yes        | Flare Slope RT (%)          | 2.8  |
| N/A        | Flare Traversable LT? | Yes    | N/A        | Flare Traversable RT?       | Yes  |
| Yes        | Landing Length (in)   | 65.0   | Yes        | DWS Provided?               | Yes  |
| Yes        | Landing Width (in)    | 50.0   | Yes        | DWS Contrast?               | Yes  |
| Yes        | Landing Slope (%)     | 0.9    | Yes        | DWS Length (in)             | 25.0 |
| No         | Landing X Slope (%)   | 3.5    | Yes        | DWS Full Width?             | Yes  |
| N/A        | Landing Curb? (Y/N)   | No     | Yes        | DWS Offset (in)             | 0.0  |
| N/A        | Shared Landing?       | No     |            |                             |      |
| Yes        | Gutter Ponding?       | No     | Yes        | Gutter Slope (%)            | 3.4  |
| Yes        | Gutter Lip Ht (in)    | 0.0    | No         | Gutter X Slope (%)          | 3.3  |
| N/A        | Painted X Walk1?      | Yes    | N/A        | Painted X Walk2?            | N/A  |
|            | X Walk 1 Direction    | To S   |            | X Walk 2 Direction          | N/A  |
| N/A        | X Walk 1 Width (in)   | 105.0  | N/A        | X Walk 2 Width (in)         | N/A  |
|            | X Walk 1 Slope (%)    | 0.7    |            | X Walk 2 Slope (%)          | N/A  |
|            | X Walk 1 X Slope (%)  | 2.3    |            | X Walk 2 X Slope (%)        | N/A  |
| Yes        | Ramp inside XWalk1?   | Yes    | N/A        | Ramp inside XWalk2?         | N/A  |
|            | Road Slope (%)        | N/A    | N/A        | Clear Space?                | Yes  |
|            | Road X Slope (%)      | N/A    | N/A        | Clear Space to XWalk (in)   | N/A  |
| Yes        | Any Obstructions?     | No     | Yes        | Storm Grate/Utility Hazard? | No   |
|            | Obstruction Type      |        |            | Storm Grate/Utility Type    |      |
|            |                       | N/A    |            |                             | N/A  |
|            |                       |        | Yes        | Surface Condition? (G/P)    | Good |

