

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 15310 Main Street: PIERSON DR **Cross Street: WOODHILL\_LN** Location: N

**ADA ID: B47A3A27ABB4** Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 8.75

## **Codes/Mitigation Info/Possible Solution**

Street 1 Name					
Stop Condition-Street 2					
Street 2 Name					
Stop Condition-Street 1					

**PIERSON DR** None **WOODHILL LN** StopSign Possible Solutions: Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent.

Surveyor Notes: N/A

PROW/ADA:

Not Found, R304.5.1





Total Cost:



3200.00

Field Measurements/Component Compliance						
Compliance Description		Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	49.0	Yes	Ramp Slope (%)	6.0	
No	Ramp Width (in)	42.5	Yes	Ramp XSlope (%)	0.4	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
	X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	5.2		X Walk 2 Slope (%)	4.6	
	X Walk 1 X Slope (%)	4.6		X Walk 2 X Slope (%)	4.3	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	0.7	N/A	Clear Space?	N/A	
	Road X Slope (%)	9.2	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	