

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 9610	Main Street: BARRINGTON_DR	Cross Street: THE_PLAZA	Location: SW
ADA ID: B482A38CFEAA	Ramp Type: ParaDiag	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 15			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.**

Surveyor Notes:

**DAMAGED SURFACE**

PROW/ADA:

**Not Found, R302.7**

Street 1 Name **BARRINGTON DR**  
 Stop Condition-Street 1 **Signal**  
 Street 2 Name **THE PLAZA**  
 Stop Condition-Street 2 **StopSign**

Total Cost: \$ 3200.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	44.0	N/A	Ramp Length RT (in)	38.0
Yes	Ramp Width LT (in)	59.5	Yes	Ramp Width RT (in)	59.0
Yes	Ramp Slope LT (%)	5.8	Yes	Ramp Slope RT (%)	5.2
Yes	Ramp XSlope LT (%)	0.2	Yes	Ramp XSlope RT (%)	0.6
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
	X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
N/A	X Walk 1 Width (in)	115.0	N/A	X Walk 2 Width (in)	114.5
	X Walk 1 Slope (%)	4.2		X Walk 2 Slope (%)	0.7
	X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	3.8
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes
	Road Slope (%)	1.6	N/A	Clear Space?	N/A
	Road X Slope (%)	5.2	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			No	Surface Condition? (G/P)	Poor
			Replace	Curb Slope (%)	15.3

