

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

Intersection ID: 7928 Main Street: HIDDEN_VALLEY_RD Cross Street: SQUIRREL_HILL_RD Location: E

ADA ID: B48F8B269462 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Compliance Description

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Data



Street 1 Name
SQUIRREL HILL RD
Stop Condition-Street 2
StopSign
Street 2 Name
N/A
Stop Condition-Street 1
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1

Total Cost: \$ 1850.00

\$ 1850.00 Obstruction Ty

Yes Ramp Slope (%) N/A Ramp Length (in) 48.0 5.6 41.5 Yes Ramp XSlope (%) No Ramp Width (in) 1.3 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A DWS Provided? N/A Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A Gutter Slope (%) N/A Yes N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? N/A X Walk 1 Direction To NW X Walk 2 Direction N/A N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) 0.9 X Walk 2 Slope (%) N/A X Walk 1 X Slope (%) 1.0 X Walk 2 X Slope (%) N/A N/A N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? N/A Road Slope (%) N/A N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A N/A Any Obstructions? N/A Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good



