cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17132 Main Street: REYNOLDS_DR				street:	SCALEYBARK_RD	Location:	Е			
ADA ID: B49C60E1457A		Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: N					
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data Compliance Description			Data	
2	Du / 3	Remove & Replace Curb Ramp W	'ith	N/A	Ramp Length (in)	70.5	Yes	Ramp Slope (%)	6.2	
	105 DR	Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	1.6	
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	Berlinson Ma			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
A STATE A	Borne 1			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
E.	Bart.	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	All Charles A	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
E. On				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
E CO	A MARCH			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
MTT2 MASS	A CONTRACTOR	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
19 1 2 2	11 - 11/1	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
e la la la la	Kale E.			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
- Alexand	<u>6</u>			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	REYNOLDS DR	-			X Walk 1 Slope (%)	2.9		X Walk 2 Slope (%)	4.4	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.3		X Walk 2 X Slope (%)	2.5	
Street 2 Name	SCALEYBARK RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	None				Road Slope (%)	1.5	N/A	Clear Space?	N/A	
					Road X Slope (%)	4.0	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	
							Yes	Surface Condition? (G/P)	Good	

