

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13936 Main Street: S\_KINGS\_DR Cross Street: CHARLOTTETOWNE\_AV Location: NE

ADA ID: B4A72D5FCFC7 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 22.5

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance



Street 1 Name	CHARLOTTETOWNE AV
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solution		
Possible Solutions:	Comp	lianc
Remove & Replace Entire Ramp.	N/A	Ra
	No	Ra
	N/A	Fla
	N/A	Fla
	N/A	Fla
	N/A	La
Surveyor Notes:	N/A	La
N/A	N/A	La
	N/A	La
	N/A	La
	N/A	Sh
PROW/ADA:	N/A	Gι
Not Found, R304.5.1, R304.2.2	N/A	Gι
	N/A	Pa
		X١
	N/A	X١
		X١
		X١
	N/A	Ra
		Ro
		Ro

-	
mann	



Total Cost:



1850.00

Field Measurements/Component Compliance							
Compl	iance Description	Data	Compl	iance	Description	Data	
N/A	Ramp Length (in)	70.0	No	Ramp	Slope (%)	9.0	
No	Ramp Width (in)	46.0	Yes	Ramp	XSlope (%)	2.2	
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A	
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A	
N/A	Painted X Walk1?	Yes	N/A	Paint	ed X Walk2?	N/A	
	X Walk 1 Direction	To SW		X Wa	lk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	110.0	N/A	X Wa	lk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	1.0		X Wa	lk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	4.4		X Wa	lk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp	inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm	n Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm	n Grate/Utility Type		
		N/A				N/A	
			Yes	Surfa	ce Condition? (G/P)	Good	