## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · ·									
Intersection ID: 2503	Intersection ID: 25033 Main Street: ARBORETUM_VIEW			Cross Street: PINEVILLE-MATTHEWS_RD				Location:	Ν
ADA ID: B4B682372F	ADA ID: B4B682372F91 Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	31.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
all a constants		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	no With	N/A	Ramp Length (in)	59.0	No	Ramp Slope (%)	9.8
The Party of				No	Ramp Width (in)	35.0	No	Ramp XSlope (%)	3.7
STRANG STR				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A AND AND				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
CELLE COLORIS	NO. NOT COM			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	THE AND			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	HALL PH			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	and the second	Not Found, R304.5.1, R304.2.2, R304.5.3	2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			<b>-</b> ,	N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
			N/A	X Walk 1 Width (in)	117.0	N/A	X Walk 2 Width (in)	104.0	
Street 1 Name	Street 1 Name ARBORETUM VIEW				X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	3.8
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	3.5		X Walk 2 X Slope (%)	0.2
Street 2 Name	PINEVILLE-MATTHEWS RD			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes
Stop Condition-Street 1	Signal				Road Slope (%)	2.0	N/A	Clear Space?	N/A
,	2.9				Road X Slope (%)	3.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	0.4 N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
		······ •				N/A			N/A
						11/7	1		10/5

**Yes** Surface Condition? (G/P)

Good

