


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 1001312	Main Street: FOGGY_MEADOW_RD	Cross Street: N/A	Location: E
ADA ID: B4E76FA8A471	Ramp Type: Para	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 0.25	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		Compliance	Description	Data
			N/A	Ramp Length LT (in)	N/A
			N/A	Ramp Width LT (in)	N/A
			N/A	Ramp Slope LT (%)	N/A
			N/A	Ramp XSlope LT (%)	N/A
			Yes	Landing Length (in)	71.0
			Yes	Landing Width (in)	118.5
			Yes	Landing Slope (%)	1.5
			No	Landing X Slope (%)	2.2
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.5.3</p>			Yes	Landing Curb? (Y/N)	No
			N/A	Shared Landing?	No
			Yes	Gutter Ponding?	No
			Yes	Gutter Lip Ht (in)	0.0
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To W
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	0.4
				X Walk 1 X Slope (%)	1.7
			N/A	Ramp inside XWalk1?	N/A
<p>Total Cost:</p> <p>\$ 1600.00</p>			N/A	Road Slope (%)	N/A
			N/A	Road X Slope (%)	N/A
			Yes	Any Obstructions?	No
				Obstruction Type	
			N/A		
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	9.5

