

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

9.3

3.1

N/A

N/A

Intersection ID: 17555Main Street:E_WOODLAWN_RDCross Street:OLD_PINEVILLE_RDLocation:SWADA ID: B50B6B330ABBRamp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:22.5

Compliance Description

N/A

No N/A

N/A

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Flare Type LT

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

38.0 No

N/A N/A

N/A N/A

No

75.0

Data Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

Flare Type RT



Street 1 Name	E WOODLAWN RD
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:
Remove & Replace Entire Ramp.
Surveyor Notes:
N/A
PROW/ADA:
Not Found, R304.5.1, R304.2.2,
R304.5.3

Total Cost:



			a. a a.apa =: (/a)			a. o o. op o (/ o /	
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N/A	Shared Landing?	N/A			
		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
5.1, R304.2.2,		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
			X Walk 1 Direction	To N		X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	112.0	N/A	X Walk 2 Width (in)	N/A
			X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	N/A
			X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	N/A
		N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	N/A	N/A	Clear Space?	N/A
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
				N/A			N/A
					Yes	Surface Condition? (G/P)	Good
	E	on the last	Land Town				