

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28312	Main Street: KRISHNA_LN			Cross Street: OLD_ARDREY_KELL_RD				Location:	NW
ADA ID: B5C084F2F8E4	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Da			ta Compliance Description		Data
		Remove & Replace Curb Ran	nn With	N/A	Ramp Length (in)	47.5	No	Ramp Slope (%)	9.4
		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	50.0	Yes	Ramp XSlope (%)	1.4
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
ARTIGUES LAN		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
and the second				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
1 States		4		N/A	Shared Landing?	N/A		DWS Onset (III)	11/2
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
					•				
A A A A A		Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
B. B.					X Walk 1 Direction	To S		X Walk 2 Direction	To E
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	KRISHNA LN				X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	0.3
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	2.3
Street 2 Name	OLD ARDREY KELL RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	0.6	N/A	Clear Space?	N/A
					Road X Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

