


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 14212	Main Street: HAWKINS_ST	Cross Street: W_TREMONT_AV	Location: NW
ADA ID: B66F6E9114CD	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 12.5			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:						
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.						
	Surveyor Notes:						
	N/A						
	PROW/ADA:						
	Not Found, R304.5.3						
				Compliance	Description	Data	Compliance
				Description	Data		Description
				Data			Data
		N/A	Ramp Length (in)	91.0	Yes	Ramp Slope (%)	5.6
		Yes	Ramp Width (in)	179.0	No	Ramp XSlope (%)	5.5
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N/A	Shared Landing?	N/A			
		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	No
			X Walk 1 Direction	To S		X Walk 2 Direction	To E
		N/A	X Walk 1 Width (in)	90.0	N/A	X Walk 2 Width (in)	N/A
			X Walk 1 Slope (%)	4.1		X Walk 2 Slope (%)	5.7
			X Walk 1 X Slope (%)	5.4		X Walk 2 X Slope (%)	1.5
		N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	5.1	N/A	Clear Space?	N/A
			Road X Slope (%)	5.5	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
			Obstruction Type			Storm Grate/Utility Type	
					N/A		N/A
		Yes	Surface Condition? (G/P)	Good			
Total Cost:		\$ 3200.00					

