

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

33.5

47.5

5.5

8.0

8.3

4.2

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 8565 Main Street: DRURY_DR Cross Street: HYDE_DR Location: SE

ADA ID: B680F87C3EE1 Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 22.5

Compliance Description

N/A

Yes

No

No

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

No

Yes

Yes

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

Flare Traversable RT?

Ramp XSlope RT (%)

Data

44.0

48.5

8.9

2.5

60.0

47.5

N/A

N/A

N/A

N/A

N/A

N/A

N/A



Street 1 Name
StopSign
Stop Condition-Street 1
HYDE DR
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.1, R304.5.3, R304.3.2





Total Cost:



1800.00

N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To N		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
	e v			Obstruction Type	
					N/A
1-1			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	1471
					N/A
			Yes	Surface Condition? (G/P)	Good
Pinopage				Curb Slope (%)	15.9