

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



l								
Intersection ID: 21432	Main Str	Cross Street: WOODSTREAM_DR			Location:	S		
ADA ID: B6A61ED73E5D	Ramp Ty	/pe: Directional1	Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	1.25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
All and the second	1. A. 19	Possible Solutions:	Compliance Description Date			a Compliance Description Data		
and the second		Remove & Replace Entire Ramp.	N/A	Ramp Lengt	th (in) <b>24.0</b>	N/A	Grade Break?	N/A
	× 113		Yes	Ramp Width	n (in) 48.0	N/A	Grade Break Slope (%)	0.0
The second second	· Aller		Yes	Ramp Slope	e (%) <b>1.1</b>	N/A	Grade Break XSlope (%)	0.0
President In the second	ATT A		No	Ramp XSlop	be (%) 4.0			
L'OOD			N/A	Flare Type L	T N/A	N/A	Flare Type RT	N/A
- Constant			N/A	Flare Slope	LT (%) N/A	N/A	Flare Slope RT (%)	0.0
La Alexandre		Surveyor Notes:	N/A	Flare Traver	sable LT? N/A	N/A	Flare Traversable RT?	N/A
	The state of the	N/A	N/A	Landing Len	gth (in) 0.0	N/A	DWS Provided?	N/A
8/ Tana	The state		N/A	Landing Wid	Ith (in) 0.0	N/A	DWS Contrast?	N/A
3	a Trop Par		N/A	Landing Slo	pe (%) 0.0	N/A	DWS Length (in)	N/A
S S S	- Carlos		N/A	Landing X S	lope (%) 0.0	N/A	DWS Full Width?	N/A
	AC SET OF	PROW/ADA:	N/A	Landing Cur	b? (Y/N) N/A	N/A	DWS Offset LT (in)	N/A
A A	A BEACH	R304.5.3	N/A	Shared Land	ding? N/A	N/A	DWS Offset RT (in)	N/A
			N/A		-	N/A	Gutter Slope (%)	N/A
	With the sum		N/A	Gutter Lip H	t (in) 0.0	N/A	Gutter X Slope (%)	N/A
	JAN TEL		N/A	Painted X W	/alk1? No		Road Slope (%)	3.2
Street 1 Name	ROCKCLIFF CT	-		X Walk 1 Dir	rection To W		Road X Slope (%)	1.4
Stop Condition-Street 1	StopSign			X Walk 1 Wi	dth (in) N/A		Clear Space?	N/A
Street 2 Name	N/A			X Walk 1 Slo	ope (%) 3.2	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A			X Walk 1 X S	Slope (%) 1.4	N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Ramp inside	XWalk1? N/A		Storm Grate/Utility Type	
			N/A	-				N/A
		Total Cost: \$ 1	600.00	Obstruction	Туре	Yes	Surface Condition? (G/P)	Good
					N/A	N/A	Curb Slope (%)	3.8

