

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 28015	Main Street: LANCASTER_HY	Cross Street: PROVIDENCE_RD_WEST	Location: SW
ADA ID: B777C12A787A	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
	Possible Solutions:		Compliance		Description	Data	Compliance		Description	Data
	Remove & Replace Entire Ramp.		N/A		Ramp Length (in)	71.0	No		Ramp Slope (%)	9.3
			Yes		Ramp Width (in)	59.0	No		Ramp XSlope (%)	2.7
			N/A		Flare Type LT	N/A	N/A		Flare Type RT	N/A
			N/A		Flare Slope LT (%)	N/A	N/A		Flare Slope RT (%)	N/A
			N/A		Flare Traversable LT?	N/A	N/A		Flare Traversable RT?	N/A
			N/A		Landing Length (in)	N/A	N/A		DWS Provided?	N/A
			N/A		Landing Width (in)	N/A	N/A		DWS Contrast?	N/A
			N/A		Landing Slope (%)	N/A	N/A		DWS Length (in)	N/A
			N/A		Landing X Slope (%)	N/A	N/A		DWS Full Width?	N/A
Surveyor Notes:		N/A		N/A		N/A		N/A		N/A
				N/A		N/A		N/A		N/A
PROW/ADA:		Not Found, R304.2.2, R304.5.3			N/A			N/A		N/A
				N/A		No		N/A		N/A
					X Walk 1 Direction	To NW			X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A		N/A	X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	0.9			X Walk 2 Slope (%)	N/A
					X Walk 1 X Slope (%)	0.2			X Walk 2 X Slope (%)	N/A
				N/A	Ramp inside XWalk1?	N/A		N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)	N/A		N/A	Clear Space?	N/A
					Road X Slope (%)	N/A		N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type				Storm Grate/Utility Type	
							N/A			N/A
								Yes	Surface Condition? (G/P)	Good
Total Cost:			\$	1850.00						
Street 1 Name		PROVIDENCE RD WEST								
Stop Condition-Street 2		Signal								
Street 2 Name		N/A								
Stop Condition-Street 1		N/A								

