

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15254 Main Street: IDEAL_WY Cross Street: PARK_RD Location: NE

Overall Compliance: No ADA ID: B7A3D39AE92E Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 18.75

Codes/Mitigation Info/Po



IDEAL WY Street 1 Name Signal Stop Condition-Street 2 Street 2 Name N/A N/A Stop Condition-Street 1

Possible Solution	
Possible Solutions:	<u>c</u>
Remove & Replace Entire Ramp.	N
Restripe Crosswalk.	N
	N
	N
	N
	N
Surveyor Notes:	N
N/A	N
	N
	N
	N
PROW/ADA:	N
R304.5.1, R304.5.3	N
	N
	N



Total Cost:



2050.00

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	liance l	Description	Data		
N/A	Ramp Length (in)	128.0	Yes	Ramp	Slope (%)	7.7		
No	Ramp Width (in)	35.0	No	Ramp 2	XSlope (%)	2.3		
N/A	Flare Type LT	N/A	N/A	Flare T	ype RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare S	Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare T	raversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS F	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS C	Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS L	ength (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS F	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS C	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutter	Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter	X Slope (%)	N/A		
N/A	Painted X Walk1?	Yes	N/A	Painted	d X Walk2?	N/A		
	X Walk 1 Direction	To S		X Walk	2 Direction	N/A		
N/A	X Walk 1 Width (in)	115.0	N/A	X Walk	2 Width (in)	N/A		
	X Walk 1 Slope (%)	5.2		X Walk	2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	0.2		X Walk	2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	No	N/A	Ramp	inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear S	Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear S	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm	Grate/Utility Type			
		N/A				N/A		
			Yes	Surface	e Condition? (G/P)	Good		

