

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17450 Main Street: NATIONS_FORD_RD Cross Street: S_TRYON_ST Location: NW

ADA ID: B7D0E3A94A4B Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 37.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name

Stop Condition-Street 2

Signal

Street 2 Name

S TRYON ST

Stop Condition-Street 1

Signal

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

	Field Measurements/Component Compnance						
Compliance De		iance Description	Data	Compliance Description		Data	
	N/A	Ramp Length (in)	56.0	No	Ramp Slope (%)	8.9	
	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	8.6	
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
		X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
		X Walk 1 Slope (%)	3.2		X Walk 2 Slope (%)	0.7	
		X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	0.2	
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
		Road Slope (%)	2.1	N/A	Clear Space?	N/A	
		Road X Slope (%)	0.4	N/A	Clear Space to XWalk (in)	N/A	
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Obstruction Type			Storm Grate/Utility Type		
			N/A			N/A	
				Yes	Surface Condition? (G/P)	Good	





