

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.0

2.4

N/A

Good

Surface Condition? (G/P)

Intersection ID: 42553 Main Street: ESTHER LN **Cross Street: TODDVILLE RD** Location: SW **ADA ID: B81EFA67E3E8** Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 1.25 Ramp Type: Perp

Codes/Mitigation Info/Pe

Field Measurements/Component Compliance



Street 1 Name	ESTHER LN
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solution	
Possible Solutions:	Co
Remove & Replace Entire Ramp.	N/A
•	Yes
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.5.3	N/A
,	N/A
	N/A
	N/A

N/A		N/A
		N/A
		N/A
		N/A
PROW/ADA:		N/A
Not Found, R304.5.3		N/A
		N/A
		N/A
		N/A
Total Cost:	\$ 1850.00	N/A

Comp	liance Description	Data	Compl	liance	Description
N/A	Ramp Length (in)	48.0	Yes	Ramp	Slope (%)
Yes	Ramp Width (in)	53.0	No	Ramp	XSlope (%)
N/A	Flare Type LT	N/A	N/A	Flare	Type RT
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?
	X Walk 1 Direction	To N		X Wa	lk 2 Direction
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)
	X Walk 1 Slope (%)	1.0		X Wa	lk 2 Slope (%)
	X Walk 1 X Slope (%)	0.4		X Wa	lk 2 X Slope (%)
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	o inside XWalk2?
	Road Slope (%)	N/A	N/A	Clear	Space?
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?
	Obstruction Type			Storn	n Grate/Utility Type





