

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Interpretion ID: 10904	10904 Main Street: ACADEMY ST								S	
Intersection ID: 10804	Main Street: ACADEMY_ST			Cross Street: HAMPSHIRE_PL				Location:		
ADA ID: B887CE9CB31C Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	No.	Possible Solutions:		Compliance Description Da			ta Compliance Description		Data	
	AND TO A	Remove & Replace Entire Ram	р.	N/A	Ramp Length (in)	72.0	No	Ramp Slope (%)	8.4	
				Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	2.0	
	100 S			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
Alean				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
A D ST CAN ST	A STREET	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
<u>ि</u>	and the second se	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
A DE ANALY AND AND AND	The second			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
MAL SALADO	a della trans			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
The state	~ 0	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	A Carling				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	ACADEMY ST				X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

