cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 51243 Main Street: NORTHCREST_SHOPPING_CENTERS SIReet: W_W_T_HARRIS_BV Location:										NE
ADA ID: B88F284501F2								0		
· · · ·										
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance Compliance Description Data Compliance Description					
	AL REAL	Possible Solutions:				liance Description				Data
	11. 1	Remove & Replace Enti	re Ran	np.	N/A	Ramp Length (in)	98.0	Yes	Ramp Slope (%)	5.1
	ALL ALL				Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.3
	1.0				N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
	1 specific states				N/A	Flare Slope LT (%)	0.7	Yes	Flare Slope RT (%)	0.6
	15 Barrow				N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
					Yes	Landing Length (in)	71.0	Yes	DWS Provided?	Yes
E A	1 The	Surveyor Notes:			Yes	Landing Width (in)	62.0	Yes	DWS Contrast?	Yes
< /7 % - 6 V	* Con Lini	N/A			No	Landing Slope (%)	2.2	Yes	DWS Length (in)	24.0
	and the state				No	Landing X Slope (%)	3.0	Yes	DWS Full Width?	Yes
NA B m Ale	Contraction of the second				N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	4.0
NA & MAR	and the second				N/A	Shared Landing?	No			
B. J. ST.	S Pro Pro	PROW/ADA:			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.7
Sil . H		Not Found, R304.2.2-Pe	rp, R3	04.3.2-	Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.9
and the		Para, R304.5.3, R305.2	• /		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
t. t.						X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
1 19				N/A	X Walk 1 Width (in)	78.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	W W T HARRIS BV					X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal					X Walk 1 X Slope (%)	2.3		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				Yes	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	Yes
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						51	N/A			N/A

s Surface Condition? (G/P)

Good

