## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interception ID: 40744	Main Ota		0	- 				Lesstien	6	
Intersection ID: 12711		Main Street: E_STONEWALL_ST		Cross Street: W_STONEWALL_ST				Location:	S	
ADA ID: B894146BF35F	Ramp Ty	Ramp Type: PerpDiag			ail: Fail Overall (	Severity Score:	22.5			
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data Compliance Description			Data	
Ros Mar	2 Carlos	Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	8.7	
1913		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	44.0	Yes	Ramp XSlope (%)	4.5	
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	E Contraction			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
Contraction of the second s	Teros .	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
PROW/ADA: R304.5.1, R304.2.2				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes	
					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW	
	L & SALE			N/A	X Walk 1 Width (in)	111.0	N/A	X Walk 2 Width (in)	109.0	
Street 1 Name	E STONEWALL ST				X Walk 1 Slope (%)	4.8		X Walk 2 Slope (%)	11.2	
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	6.4		X Walk 2 X Slope (%)	2.1	
Street 2 Name	S TRYON ST			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes	
Stop Condition-Street 1	Signal				Road Slope (%)	6.4	N/A	Clear Space?	N/A	
	-				Road X Slope (%)	4.2	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	
							Yes	Surface Condition? (G/P)	Good	

