

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 10024336 Main Street: CREEKRIDGE\_RD Cross Street: N/A Location: SE **Overall Compliance: No** ADA ID: B8CAD90219AE Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 25

**Codes/Mitigation Info/Possible Solution** 

## **Field Measurements/Component Compliance**



CONTRACTOR OF THE PARTY OF THE	
Street 1 Name	ENTRANCE
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

ossible Solutions:	<u>c</u>
Remove & Replace Entire Ramp.	
•	Υ
	N
	N
	N
	N
ırveyor Notes:	N
N/A	N
	N
	N
	N
ROW/ADA:	N
R304.2.2	N
	N
	N
	N

lition-Street 2	None	
ame	N/A	
lition-Street 1	N/A	
		Total Cost:

Comp	oliance Description	Data	Comp	liance Description	Data
N/A	Ramp Length (in)	64.0	No	Ramp Slope (%)	14.9
Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.1
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	5.9		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	14.5		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good







1850.00