

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10033044 Main Street: NOLLEY_CT Cross Street: N/A Location: SE **Overall Compliance: No** ADA ID: B90DB878D1F4 Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



NOLLEY CT Street 1 Name Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:						
Remove & Replace Entire Ramp.						
Surveyor Notes:						
N/A						
N/A						
PROW/ADA:						
R304.5.1						

9	TROWADA.		
The state of the s	R304.5.1		1
			I
			ı
	Total Cost:	\$ 1850.00	ı

N/A	Landing Cur
N/A	Shared Land
N/A	Gutter Pond
N/A	Gutter Lip H
N/A	Painted X W
	X Walk 1 Dir
N/A	X Walk 1 Wi
	X Walk 1 Slo
	X Walk 1 X S
N/A	Ramp inside
	Road Slope
	Road X Slop
N/A	Any Obstruc
	Obstruction
1	William Tel
	*
AND.	
- 24	
	harte

Comp	liance Description	Data		liance Description	Data
N/A	Ramp Length (in)	97.0	Yes Ramp Slope (%)		5.8
No	Ramp Width (in)	46.0	Yes Ramp XSlope (%)		0.4
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A DWS Provided?		N/A
N/A	Landing Width (in)	N/A	N/A DWS Contrast?		N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.4		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good





