## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11299 Main Street: S_SUMMIT_AV Cross Street: W_4TH_ST							Location	E	
	Main Street: S_SUMMIT_AV				Location:	E			
ADA ID: B9179CB84AB7 Ramp Type: PerpDiag		Initial Pas	ss/Fa	ail: Fail Overall (	o Severity Score:	12.5			
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:	<u>(</u>	Compliance Description			Data Compliance Description		Data	
	Remove & Replace Curb Ramp	Nith N	N/A	Ramp Length (in)	47.0	No	Ramp Slope (%)	9.2	
	Two New Directional Ramps or Equivalent.		/es	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.9	
		Ν	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		Ν	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		Ν	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	· · · · · · · · · · · · · · · · · · ·	Ν	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	Ν	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	Ν	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
E B ST		Ν	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
0 6 0		Ν	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
The second second	A STATE OF S	M	N/A	Shared Landing?	N/A				
A RANGE	PROW/ADA:	Ν	N/A	Gutter Ponding?	Yes	N/A	Gutter Slope (%)	N/A	
the the second second	R304.2.2	Ν	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stall And Ship of - 10		N	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
	2			X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
at the asset of the		N	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name S SUMMI	ΓAV			X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	1.7	
Stop Condition-Street 2	lone			X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	2.3	
Street 2 Name W 4T	H ST	N	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 Stop	Sign			Road Slope (%)	0.6	N/A	Clear Space?	N/A	
				Road X Slope (%)	2.9	N/A	Clear Space to XWalk (in)	N/A	
		١	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A	

**Yes** Surface Condition? (G/P)

Good

