

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10040093 Main Street: TUCKASEEGEE_RD Cross Street: N/A Location: **Overall Compliance: No** ADA ID: B936B5686882 Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 33.75

Codes/Mitigation Info/Possible Solution



Street 1 Name **TUCKASEEGEE RD** Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:						
Remove & Replace Entire Ramp.						
·						
Surveyor Notes:						
N/A						
N/A						
PROW/ADA:						
Not Found, R304.5.1, R304.2.2						

Surveyor Notes:			N/A
N/A			N/A
			N/A
			N/A
			N/A
PROW/ADA:			N/A
Not Found, R304.5.1, R3	2	N/A	
			N/A
			N/A
			N/A
Total Cook	•	4050.00	N/A
Total Cost:	\$	1850.00	

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	liance Description	Data			
N/A	Ramp Length (in)	49.0	No	Ramp Slope (%)	13.2			
No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	0.9			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A			
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A			
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A			
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A			
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A			
	X Walk 1 Direction	To S		X Walk 2 Direction	N/A			
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A			
	X Walk 1 Slope (%)	4.5		X Walk 2 Slope (%)	N/A			
	X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A			
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A			
	Road Slope (%)	N/A	N/A	Clear Space?	N/A			
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A			
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm Grate/Utility Type				
		N/A			N/A			
			Yes	Surface Condition? (G/P)	Good			
2000								





