

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8094	Main Street: KNOLLCREST_DR			Cross Street: S_RAMSEY_ST				Location:	Ν	
ADA ID: B94F1418CDC7	C7 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance:			ice: No	o Severity Score:	1.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description Data			Compliance Description D		Data	
A CARACTER OF A	Mar C.	Remove & Replace Entire Ramp		N/A	Ramp Length (in)	24.0	Yes	Ramp Slope (%)	5.8	
Vi Juli On V		· · · · · · · · · · · · · · · · · · ·	-	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.6	
	*/			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
Letter and the second s	12.			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	1 2			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	Str 4			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
P &		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	AN	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	1			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
150				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
A BOULT AND AND	AT IN			N/A	Shared Landing?	N/A				
	~ ~ ~	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
and the second second	A SEA	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	A 12 10			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name KNOL	LCREST DR	_			X Walk 1 Slope (%)	0.0		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	5.0		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

s Surface Condition? (G/P)

Good

