

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 44913Main Street:SPRINGHAVEN_DRCross Street:OAK_DRLocation:NWADA ID: B97505F7FB8BRamp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
None
Street 2 Name
OAK DR
Stop Condition-Street 1
StopSign

Possible Solutions:				
Remove & Replace Curb Ramp With				
Two New Directional Ramps or	I			
Equivalent.	ı			
	ı			
	ı			
	ı			
Surveyor Notes:	I			
N/A	I			
	I			
	ı			
	ı			
PROW/ADA:	I			
Not Found, R304.5.1, R304.2.2	I			
	I			

Total Cost:	\$ 3200.00	

	Field Measure	ments/C	ompo	nent Compliance	
Compliance Description			Comp	liance Description	Data
N/A	Ramp Length (in)	45.0	No	Ramp Slope (%)	9.9
No	Ramp Width (in)	36.0	Yes	Ramp XSlope (%)	0.7
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To S		X Walk 2 Direction	To E
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	2.5
	X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	2.3
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	0.9	N/A	Clear Space?	N/A
	Road X Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good





