

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10037315Main Street: SARDIS_RDCross Street: N/ALocation: NEADA ID: BAC5336AAEB2Ramp Type: PerpDiagInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 37.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

SARDIS RD None ENTRANCE StopSign Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

| Compliance Description | | Data | Compliance Description | | Data | |
|------------------------|-----------------------|-------|------------------------|-----------------------------|-------|--|
| N/A | Ramp Length (in) | 52.0 | No | Ramp Slope (%) | 10.2 | |
| Yes | Ramp Width (in) | 59.0 | No | Ramp XSlope (%) | 7.8 | |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| N/A | Shared Landing? | N/A | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No | |
| | X Walk 1 Direction | To SW | | X Walk 2 Direction | To SE | |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | |
| | X Walk 1 Slope (%) | 2.4 | | X Walk 2 Slope (%) | 0.8 | |
| | X Walk 1 X Slope (%) | 4.7 | | X Walk 2 X Slope (%) | 3.5 | |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| | Road Slope (%) | 1.9 | N/A | Clear Space? | N/A | |
| | Road X Slope (%) | 0.4 | N/A | Clear Space to XWalk (in) | N/A | |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | N/A | | | N/A | |
| | | | | | | |

Yes

Surface Condition? (G/P)

Good





