

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13936Main Street: S_KINGS_DRCross Street: CHARLOTTETOWNE_AVLocation:SWADA ID: BAD7AC35A499Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score:25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
CHARLOTTETOWNE AV
Stop Condition-Street 2
Signal
Street 2 Name
N/A
Stop Condition-Street 1
N/A

Possible Solutions:	Com
Remove & Replace Entire Ramp.	N/A
·	Yes
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.5.3	N/A
	N/A
	N/A
	N/A



Total Cost:



1850.00

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	liance	Description	Data		
N/A	Ramp Length (in)	48.0	Yes	Ramp	Slope (%)	5.4		
Yes	Ramp Width (in)	48.0	No	Ramp	XSlope (%)	7.1		
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutte	Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	X Slope (%)	N/A		
N/A	Painted X Walk1?	Yes	N/A	Painte	ed X Walk2?	N/A		
	X Walk 1 Direction	To N		X Wal	k 2 Direction	N/A		
N/A	X Walk 1 Width (in)	111.0	N/A	X Wal	k 2 Width (in)	N/A		
	X Walk 1 Slope (%)	0.1		X Wal	k 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	5.0		X Wal	k 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp	inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm	Grate/Utility Type			
		N/A				N/A		
			Yes	Surfac	ce Condition? (G/P)	Good		
		·	-					