


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 15882	Main Street: EAST_BV	Cross Street: QUEENS_RD_WEST	Location: N
ADA ID: BAD7F6064B8D	Ramp Type: MedianPerp	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 17.75

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance			
	Possible Solutions:	Remove & Replace Entire Ramp.	Compliance	Description	Data
		Grind Gutter Lip.	Compliance	Description	Data
	Surveyor Notes:	N/A	N/A	Ramp Length (in)	73.0
			Yes	Ramp Width (in)	59.5
			N/A	Flare Type LT	Sloped
			N/A	Flare Slope LT (%)	9.5
			N/A	Flare Traversable LT?	No
			Yes	Landing Length (in)	62.0
			Yes	Landing Width (in)	58.0
			Yes	Landing Slope (%)	0.0
<p>PROW/ADA:</p> <p>R304.5.3, R305.1.4, R305.2, R302.7.2</p>			Yes	Flare Slope RT (%)	8.4
			N/A	Flare Traversable RT?	No
			Yes	DWS Provided?	Yes
			Yes	DWS Contrast?	Yes
			Yes	DWS Length (in)	24.0
			No	DWS Full Width?	No
			No	DWS Offset (in)	4.0
			N/A	Shared Landing?	No
			Yes	Gutter Ponding?	No
			No	Gutter Lip Ht (in)	1.0
<p>Total Cost:</p> <p>\$ 1850.00</p>			Yes	Gutter X Slope (%)	0.4
			N/A	Painted X Walk1?	Yes
			N/A	X Walk 1 Direction	To N
			N/A	X Walk 1 Width (in)	110.0
			N/A	X Walk 1 Slope (%)	0.4
			N/A	X Walk 1 X Slope (%)	0.7
			Yes	Ramp inside XWalk1?	Yes
			N/A	Road Slope (%)	N/A
			N/A	Road X Slope (%)	N/A
			Yes	Any Obstructions?	No
<p>Obstruction Type</p>			N/A	Storm Grate/Utility Hazard?	No
			N/A	Storm Grate/Utility Type	N/A
			Yes	Surface Condition? (G/P)	Good

