

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|---|---------------------------|---|------------------------|
| Intersection ID: N/A | Main Street: CRESSWIND BV | Cross Street: SILVER SPRINGS CT | Location: SE |
| ADA ID: BB7F725A64C1 | Ramp Type: Directional1 | Initial Pass/Fail: Pass | Overall Compliance: No |
| | | Severity Score: 5.25 | |
| Codes/Mitigation Info/Possible Solution | | Field Measurements/Component Compliance | |



Possible Solutions:

**Remove & Replace Entire Ramp.
Gutter Ponding Observed.**

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3, R304.2.3, R302.7

Total Cost: \$ 2100.00

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-----------------------|------|------------|-----------------------------|------|
| N/A | Ramp Length (in) | 57.0 | Yes | Grade Break? | Yes |
| Yes | Ramp Width (in) | 96.0 | No | Grade Break Slope (%) | 5.4 |
| Yes | Ramp Slope (%) | 3.5 | No | Grade Break XSlope (%) | 2.9 |
| No | Ramp XSlope (%) | 2.5 | | | |
| Yes | Flare Type LT | N/A | No | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | No | N/A | Flare Traversable RT? | No |
| Yes | Landing Length (in) | 95.0 | Yes | DWS Provided? | Yes |
| Yes | Landing Width (in) | 97.0 | Yes | DWS Contrast? | Yes |
| Yes | Landing Slope (%) | 1.8 | Yes | DWS Length (in) | 24.0 |
| No | Landing X Slope (%) | 3.2 | Yes | DWS Full Width? | Yes |
| N/A | Landing Curb? (Y/N) | N/A | Yes | DWS Offset LT (in) | 54.0 |
| N/A | Shared Landing? | Yes | Yes | DWS Offset RT (in) | 0.0 |
| No | Gutter Ponding? | Yes | Yes | Gutter Slope (%) | 1.7 |
| Yes | Gutter Lip Ht (in) | 0.0 | Yes | Gutter X Slope (%) | 1.5 |
| N/A | Painted X Walk1? | No | | Road Slope (%) | 0.0 |
| | X Walk 1 Direction | To N | | Road X Slope (%) | 0.2 |
| | X Walk 1 Width (in) | N/A | | Clear Space? | Yes |
| | X Walk 1 Slope (%) | 0.0 | N/A | Clear Space to XWalk (in) | N/A |
| | X Walk 1 X Slope (%) | 0.2 | Yes | Storm Grate/Utility Hazard? | No |
| N/A | Ramp inside XWalk1? | N/A | | Storm Grate/Utility Type | |
| Yes | Any Obstructions? | No | | | N/A |
| | Obstruction Type | | Yes | Surface Condition? (G/P) | Good |
| | | | N/A | Curb Slope (%) | 6.5 |

| | |
|-------------------------|--------------|
| Street 1 Name | CRESSWIND BV |
| Stop Condition-Street 1 | None |
| Street 2 Name | N/A |
| Stop Condition-Street 2 | N/A |

