

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 31895 Main Street: SLALOM HILL RD Cross Street: STOWE DERBY DR Location: **ADA ID: BBA88D3C2518** Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 10

**Codes/Mitigation Info/Possible Solution** 



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 STOWE DERBY DR None **SLALOM HILL RD** StopSign

Possible Solutions: Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent. Surveyor Notes: N/A PROW/ADA: R304.5.1, R304.5.3

Total Cost: 3200.00

Field Measurements/Component Compliance								
	Compli	ance Description		Data	Compliance		Description	Data
	N/A	Ramp	Length (in)	47.0	Yes	Ramp	Slope (%)	6.7
	No	Ramp	Width (in)	41.0	No	Ramp	XSlope (%)	3.5
	N/A	Flare	Type LT	N/A	N/A	Flare	Type RT	N/A
	N/A	Flare	Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
	N/A	Flare	Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
	N/A	Landii	ng Length (in)	N/A	N/A	DWS	Provided?	N/A
	N/A	Landii	ng Width (in)	N/A	N/A	DWS	Contrast?	N/A
	N/A	Landii	ng Slope (%)	N/A	N/A	DWS	Length (in)	N/A
	N/A	Landii	ng X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
	N/A	Landii	ng Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
	N/A	Share	d Landing?	N/A				
	N/A	Gutte	r Ponding?	N/A	N/A	Gutte	Slope (%)	N/A
	N/A	Gutte	r Lip Ht (in)	N/A	N/A	Gutte	X Slope (%)	N/A
	N/A	Painte	ed X Walk1?	No	N/A	Painte	ed X Walk2?	No
		X Wal	k 1 Direction	To SW		X Wal	k 2 Direction	To SE
	N/A	X Wal	k 1 Width (in)	N/A	N/A	X Wal	k 2 Width (in)	N/A
		X Wal	k 1 Slope (%)	2.8		X Wal	k 2 Slope (%)	2.3
		X Wal	k 1 X Slope (%)	1.4		X Wal	k 2 X Slope (%)	2.4
	N/A	Ramp	inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
		Road	Slope (%)	2.2	N/A	Clear	Space?	N/A
		Road	X Slope (%)	4.6	N/A	Clear	Space to XWalk (in)	N/A
	N/A	Any C	bstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
		Obstr	uction Type			Storm	Grate/Utility Type	
				N/A				N/A
					Yes	Surfac	ce Condition? (G/P)	Good
	1000	ANA	- K					





