


Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10025543Main Street: E_TRADE_STCross Street: N/ALocation:WADA ID: BBDBE40895F3Ramp Type: Directional1Initial Pass/Fail: FailOverall Compliance: NoSeverity Score: 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name	E TRADE ST
Stop Condition-Street 1	Signal
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3

Total Cost:	\$ 1600.00

Field Measurements/Component Compliance								
Compl	iance Description	Data	Comp	liance Description	Data			
N/A	Ramp Length (in)	48.0	N/A	Grade Break?	N/A			
Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0			
Yes	Ramp Slope (%)	2.3	N/A	Grade Break XSlope (%)	0.0			
No	Ramp XSlope (%)	5.7						
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A			
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A			
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A			
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A			
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A			
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk1?	No		Road Slope (%)	1.0			
	X Walk 1 Direction	To SE		Road X Slope (%)	5.9			
	X Walk 1 Width (in)	N/A		Clear Space?	N/A			
	X Walk 1 Slope (%)	1.0	N/A	Clear Space to XWalk (in)	N/A			
	X Walk 1 X Slope (%)	5.9	N/A	Storm Grate/Utility Hazard?	N/A			
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type				
N/A	Any Obstructions?	N/A			N/A			
	Obstruction Type		Yes	Surface Condition? (G/P)	Good			
		N/A	N/A	Curb Slope (%)	3.8			





