

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

65.5

46.0

5.0

3.9

3.9

2.6

N/A

No

N/A

2.6

4.3

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Good 19.2

Intersection ID: N/A Main Street: BURTON ST **Cross Street: HAMILTON ST** Location: NW **Overall Compliance: No Severity Score: ADA ID: BBE652C7723D** Ramp Type: Combination2Diag Initial Pass/Fail: Fail 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance




Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

StopSign **BURTON ST** None **HAMILTON ST**

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.5.3

Total Cost: 3200.00



N/A

6.4

1.9

N/A

1.5

6.6

N/A

N/A

N/A

N/A

Yes

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Any Obstruction?

Obstruction Type

Curb Slope (%)







N/A

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)