cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 47976	Main Street: AVALY_LN			Street:	ARDREY_KELL_RD	Location:	NW		
ADA ID: BBEBEB1A5D93	5D93 Ramp Type: PerpDiag		Initial F	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data Complian			liance Description	Data	
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	88.0	No	Ramp Slope (%)	10.8
		Two New Directional Ramps or		No	Ramp Width (in)	46.5	Yes	Ramp XSlope (%)	0.9
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
A CONTRACTOR		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
All and a second				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
EN m	L RD			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
ARDREN	Constant of			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
The second s				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
CONTRACTOR OF					X Walk 1 Direction	To S		X Walk 2 Direction	To E
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ARDREY KELL RD				X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	0.8
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	1.2
Street 2 Name	AVALY LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	1.4	N/A	Clear Space?	N/A
					Road X Slope (%)	0.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
4							I		

Yes Surface Condition? (G/P)

Good

