

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Main Str	Main Street: ORCHID_BRDIGE_RD			PUMPERNICKEL_RD	Location:	NW		
ADA ID: BC040426B810	Ramp Ty	Ramp Type: Perp			il: Fail Overall	nce: N	o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
		Possible Solutions:	Compliance Description Data C				Comp	Compliance Description	
		Remove & Replace Entire Ramp.	N/A	Α	Ramp Length (in)	102.0	No	Ramp Slope (%)	8.4
	S 31		Ye	s	Ramp Width (in)	92.0	No	Ramp XSlope (%)	3.5
200			N//	Α	Flare Type LT	N/A	N/A	Flare Type RT	N/A
ALE ALE	(FP	1	N/.	Α	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
TELES A	ADG. A		N/2	Α	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	5		N//	Α	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Contraction of the contraction o	Surveyor Notes:	N/2	Α	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	5 <u>6</u>	N/A	N//	Α	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	Mr. Carlos		N/	Α	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A A A A A A A A A A A A A A A A A A A			N/2	Α	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	A ALCON		N/2	Α	Shared Landing?	N/A			
the state		PROW/ADA:	N/2	Α	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
and the second		R304.2.2, R304.5.3	N//	A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
6	aller N. N.		N/2	Α	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
A. Yo					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
	1. 1. N. 1		N/	Α	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name PU	IMPERNICKLE RD	_			X Walk 1 Slope (%)	2.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/	Α	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/.	A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$1	850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

