


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 53624	Main Street: PROSPERITY RIDGE RD	Cross Street: RIDGE RD	Location: NW
ADA ID: BC0F8ED72C66	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	129.0	N/A	Grade Break?	N/A
			Yes	Ramp Width (in)	68.0	N/A	Grade Break Slope (%)	0.0
			No	Ramp Slope (%)	10.5	N/A	Grade Break XSlope (%)	0.0
			No	Ramp XSlope (%)	2.2			
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	Surveyor Notes:		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
				Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
			Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
			Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
		R304.2.2, R304.5.3	N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	Yes		Road Slope (%)	1.2
				X Walk 1 Direction	To NE		Road X Slope (%)	2.1
				X Walk 1 Width (in)	113.5		Clear Space?	N/A
				X Walk 1 Slope (%)	1.2	N/A	Clear Space to XWalk (in)	N/A
				X Walk 1 X Slope (%)	2.1	N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
			N/A	Any Obstructions?	N/A			N/A
				Obstruction Type		Yes	Surface Condition? (G/P)	Good
					N/A	N/A	Curb Slope (%)	N/A
Total Cost:		\$ 1600.00						
Street 1 Name			PROSPERITY RIDGE RD					
Stop Condition-Street 1			Signal					
Street 2 Name			N/A					
Stop Condition-Street 2			N/A					

