cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18282	18282 Main Street: RAMA_RD				RIVIERE_DR	Location:	SW		
ADA ID: BC1B4A1050CC	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No					
			initial F						13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
ENVIERE DIR C.	5	Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Curb Ramp Wir Two New Directional Ramps or Equivalent.	Nith	N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	9.9
				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.6
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A		ζ,	
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A
Contraction of the		Not i build, 1(304.2.2, 1(304.3.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
a set of the					X Walk 1 Direction	To E		X Walk 2 Direction	To N
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	RAMA RD			11/4	X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	0.1
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	0.1 1.4
Stop Condition-Street 2	RIVIERE DR			N/A	• • • •	0.0 N/A	N/A	,	1.4 N/A
				N/A	Ramp inside XWalk1?			Ramp inside XWalk2?	
Stop Condition-Street 1	StopSign				Road Slope (%)	2.8	N/A	Clear Space?	N/A
					Road X Slope (%)	1.0	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

