## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28773 Main S	Main Street: ROYAL_HIGHLANDS_CT			THATCHER_HALL_C		Location:	SE	
ADA ID: BC24CC00907E Ramp	Ramp Type: Perp			ail: Pass Overall	ce: N	o Severity Score:	15	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description			Data Compliance Description		
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	47.5	Yes	Ramp Slope (%)	6.6
	Remove & Replace Gutter.		Yes	Ramp Width (in)	60.0	Yes	Ramp XSlope (%)	1.1
			N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	3.0	Yes	Flare Slope RT (%)	6.0
			N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
			No	Landing Length (in)	47.5	No	DWS Provided?	No
THATCHER HOLL OF	Surveyor Notes:		Yes	Landing Width (in)	60.0	N/A	DWS Contrast?	No
	N/A		No	Landing Slope (%)	2.4	N/A	DWS Length (in)	N/A
			Yes	Landing X Slope (%)	1.1	N/A	DWS Full Width?	No
			N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
1 1 1 1 1 1 1			N/A	Shared Landing?	No			
	PROW/ADA:		Yes	Gutter Ponding?	No	No	Gutter Slope (%)	5.4
	Not Found, R304.2.1, R304.2.2-Pe	erp,	Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.8
	R304.3.2-Para, R305, R304.5.4	• *	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To W		X Walk 2 Direction	N/A
CARLE CARLENAL MERICE			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name ROYAL HIGHLANDS CT	r			X Walk 1 Slope (%)	2.9		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 None				X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A	A Contraction of the second seco		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A	A Contraction of the second seco			Road Slope (%)	N/A	N/A	Clear Space?	Yes
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Total Cost: \$ 2	2600.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

s Surface Condition? (G/P)

Good

