

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Obstruction Type

Curb Slope (%)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

Yes

N/A

N/A

N/A

1.6

Good

Intersection ID: 13099	Main Street: TRADE_ST				Street:	MCDOWELL_ST	Location:	Ν		
ADA ID: BC9638A3F8A9	Ramp Ty	Ramp Type: Combination2			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description Data Compliance				liance Description	Data
		Remove & Replace En	tire Rar	np.	N/A	Ramp Length LT (in)	49.0	N/A	Ramp Length RT (in)	N/A
					Yes	Ramp Width LT (in)	49.0	N/A	Ramp Width RT (in)	N/A
	1111				No	Ramp Slope LT (%)	11.2	N/A	Ramp Slope RT (%)	N/A
					Yes	Ramp XSlope LT (%)	1.1	N/A	Ramp XSlope RT (%)	N/A
to.	E CAL				N/A	Ramp Length (in)	24.0	Yes	Ramp Slope (%)	7.0
	all a				Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.6
	(DONE)	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
这 <u></u> <u></u> <u></u> <u></u> <u></u> <u></u>	The .	N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	the second second				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	6. C				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	<u>6</u>	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
COULS -	Real And And	R304.3.2			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
a light	AND AND				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	the second				N/A	Shared Landing?	N/A			
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	Signal				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	N MCDOWELL ST				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	110.0		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$	1600.00	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				m Ci-II				N/A	Any Obstruction?	N/A





