


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | | | | | | | | | |
|--|--|---------------------------------|----------------------|---|-----|-----------------------------|-----------------------|-------------------|-----|------------------------|-----|
| Intersection ID: N/A | | Main Street: UNIVERSITY_CITY_BV | | Cross Street: N/A | | Location: NE | | | | | |
| ADA ID: BC9FC1FBF340 | | Ramp Type: Directional1 | | Initial Pass/Fail: Pass | | Overall Compliance: No | | Severity Score: 5 | | | |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | | | |
|  <div>Street 1 NameENTRANCE</div> <div>Stop Condition-Street 1StopSign</div> <div>Street 2 NameN/A</div> <div>Stop Condition-Street 2N/A</div> | | | | Possible Solutions: | | Compliance | | Description | | Data | |
| | | | | Remove & Replace Entire Ramp. | | N/A | Ramp Length (in) | 122.0 | Yes | Grade Break? | Yes |
| | | | | Remove & Replace Gutter. | | Yes | Ramp Width (in) | 71.0 | Yes | Grade Break Slope (%) | 1.3 |
| | | | | | | Yes | Ramp Slope (%) | 1.6 | No | Grade Break XSlope (%) | 6.2 |
| | | | | | | Yes | Ramp XSlope (%) | 1.7 | | | |
| | | | | | | Yes | Flare Type LT | N/A | Yes | Flare Type RT | N/A |
| | | | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | | | | N/A | Flare Traversable LT? | No | N/A | Flare Traversable RT? | No |
| | | | | | | Yes | Landing Length (in) | 63.0 | Yes | DWS Provided? | Yes |
| | | | | | | Yes | Landing Width (in) | 72.0 | Yes | DWS Contrast? | Yes |
| | | No | Landing Slope (%) | 4.3 | Yes | DWS Length (in) | 24.0 | | | | |
| | | Yes | Landing X Slope (%) | 1.5 | Yes | DWS Full Width? | Yes | | | | |
| | | N/A | Landing Curb? (Y/N) | N/A | Yes | DWS Offset LT (in) | 28.0 | | | | |
| | | N/A | Shared Landing? | No | No | DWS Offset RT (in) | 8.0 | | | | |
| | | Yes | Gutter Ponding? | No | No | Gutter Slope (%) | 8.1 | | | | |
| | | Yes | Gutter Lip Ht (in) | 0.0 | No | Gutter X Slope (%) | 6.0 | | | | |
| | | N/A | Painted X Walk1? | No | | Road Slope (%) | 2.2 | | | | |
| | | | X Walk 1 Direction | To SW | | Road X Slope (%) | 6.7 | | | | |
| | | | X Walk 1 Width (in) | N/A | | Clear Space? | Yes | | | | |
| | | | X Walk 1 Slope (%) | 2.2 | N/A | Clear Space to XWalk (in) | N/A | | | | |
| | | | X Walk 1 X Slope (%) | 6.7 | Yes | Storm Grate/Utility Hazard? | No | | | | |
| | | N/A | Ramp inside XWalk1? | N/A | | Storm Grate/Utility Type | | | | | |
| | | Yes | Any Obstructions? | No | | | N/A | | | | |
| | | | Obstruction Type | | Yes | Surface Condition? (G/P) | Good | | | | |
| | | | | | N/A | Curb Slope (%) | 7.3 | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

