


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 29367	Main Street: MOSSY_OAK_LN	Cross Street: SUMMIT_HILLS_DR	Location: SE
ADA ID: BCC7D2C4695F	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 21.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		Yes	Ramp Length (in)	7.4
			No	Ramp Width (in)	5.1
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.5.1, R304.5.3</p>			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			No	Painted X Walk1?	No
				X Walk 1 Direction	To N
			N/A	X Walk 1 Width (in)	N/A
			7.0	X Walk 1 Slope (%)	2.2
			0.7	X Walk 1 X Slope (%)	4.4
			N/A	Ramp inside XWalk1?	N/A
			2.1	Road Slope (%)	N/A
			3.6	Road X Slope (%)	N/A
			N/A	Any Obstructions?	N/A
			N/A	Obstruction Type	N/A
			N/A		N/A
			N/A		N/A
			N/A		N/A
			N/A		N/A
			N/A		N/A
			N/A		N/A
			N/A		N/A
			N/A		N/A
			N/A		N/A
Total Cost:			\$	3200.00	

Street 1 Name **MOSSY OAKS LN**

Stop Condition-Street 2 **StopSign**

Street 2 Name **SUMMIT HILLS DR**

Stop Condition-Street 1 **None**

