cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27297 Main Street: BALLANTYNE_COMMONS_PY Cross Street: BRITTANY_OAKS_DR								Location:	W		
ADA ID: BCF2E8447F0A	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance				o Severity Score:	13.75		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description		Data Compliance Description			Data		
	A 1 65	Remove & Replace Entire Ramp		N/A	Ramp Length (in)	72.0	N/A	Grade Break?	N/A		
And And And				Yes	Ramp Width (in)	60.0	N/A	Grade Break Slope (%)	0.0		
	a contraction			No	Ramp Slope (%)	8.4	N/A	Grade Break XSlope (%)	0.0		
				No	Ramp XSlope (%)	2.6					
E Ray E	12			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
State Barris				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0		
TR. A. FORMAN	A A	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
<u>स</u>		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A		
A Martine	MONS PU			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A		
ATTALE OF				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A		
EALWAND	ALACTING TAN			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A		
and the	and the second	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A		
ANT CONTRACTOR	The start	R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A		
Sala an	- The			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A		
and the set where				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A		
				N/A	Painted X Walk1?	No		Road Slope (%)	3.7		
Street 1 Name	BRITTANY OAKS DR				X Walk 1 Direction	To NE		Road X Slope (%)	2.3		
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A		
Street 2 Name	N/A				X Walk 1 Slope (%)	3.7	N/A	Clear Space to XWalk (in)	N/A		
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	2.3	N/A	Storm Grate/Utility Hazard?	N/A		
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type			
				N/A	Any Obstructions?	N/A			N/A		
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good		
						N/A	N/A	Curb Slope (%)	0.2		

