

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15870	Main Street: CHEROKEE_RD		Cross Street: HUNTLEY_PL				Location:	SW
ADA ID: BD37B11A88EE	037B11A88EE Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	1.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:					Compliance Description Data		
P O S	Remove & Replace Entir	re Ramp.	N/A	Ramp Length (in)	71.0	N/A	Grade Break?	N/A
		· · · · · · · · · · · · · · · · · · ·	Yes	Ramp Width (in)	58.0	N/A	Grade Break Slope (%)	0.0
			Yes	Ramp Slope (%)	2.1	N/A	Grade Break XSlope (%)	0.0
			No	Ramp XSlope (%)	2.9			
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
HUNTLEY PL 50			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
A A A A A A A A A A A A A A A A A A A			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
and I have a series of the ser	R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
A DESCRIPTION			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	Contraction of the second		N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	Yes		Road Slope (%)	2.1
Street 1 Name HUN	TLEY PL			X Walk 1 Direction	To N		Road X Slope (%)	1.6
Stop Condition-Street 1 S	StopSign			X Walk 1 Width (in)	128.0		Clear Space?	N/A
Street 2 Name	N/A			X Walk 1 Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A			X Walk 1 X Slope (%)	1.6	N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
			N/A	Any Obstructions?	N/A			N/A
	Total Cost:	\$ 1600.	00	Obstruction Type		Yes	Surface Condition? (G/P)	Good
					N/A	N/A	Curb Slope (%)	5.2

