## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



		ι	-	/					
Intersection ID: 14032	Main Str	eet: REID_AV	Cross S	Street:	WEST_BV			Location:	SE
ADA ID: BDB39B286BB7	Ramp Ty	ype: Combination2Diag	Initial P	ass/Fa	ail: Fail Overall C	omplian	ce: N	o Severity Score:	0
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance									
		Possible Solutions:		Compl	liance Description	Data	Comp	liance Description	Data
		Remove & Replace Curb Ramp	With	N/A	Ramp Length LT (in)	60.0	N/A	Ramp Length RT (in)	N/A
		Two New Directional Ramps or		No	Ramp Width LT (in)	40.0	N/A	Ramp Width RT (in)	N/A
		Equivalent.		No	Ramp Slope LT (%)	10.5	N/A	Ramp Slope RT (%)	N/A
		4		Yes	Ramp XSlope LT (%)	0.1	N/A	Ramp XSlope RT (%)	N/A
				N/A	Ramp Length (in)	45.0	Yes	Ramp Slope (%)	0.4
				No	Ramp Width (in)	42.5	No	Ramp XSlope (%)	5.4
1 12 1	- //	Surveyor Notes:		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	the second	VEGETATION OVERGROWTH		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	2 ar			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	TT			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		PROW/ADA:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	-r in	R304.5.1, R304.5.1, R304.5.3,		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
MARKES & LEPA.		R304.3.2		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
all and the				N/A	Shared Landing?	N/A			
	and the second			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	None			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	WEST BV			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Street 2 Name	StopSign				X Walk 1 Direction	To N		X Walk 2 Direction	To W
Stop Condition-Street 2	<b>REID AV</b>				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	5.0		X Walk 2 Slope (%)	3.8
					X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	6.5
		Total Cost: \$ 3	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)	4.8		Clear Space?	N/A
					Road X Slope (%)	6.9	N/A	Clear Space to XWalk (in)	N/A
	The A			and the se			N/A	Any Obstruction?	N/A
R Storf & Look State								Obstruction Type	
	P P		12						N/A

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A

Yes	Surface Condition? (G/P)	Good
	Curb Slope (%)	0.8





