

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12445 Main Street: CHESTNUT_AV Cross Street: THE_PLAZA Location: NE **Overall Compliance: No** ADA ID: BDB6EF0D4DCD Ramp Type: Directional1 Initial Pass/Fail: Fail **Severity Score:** 12.5

Codes/Mitigation Info/Po



Street 1 Name	CHESTNUT AV
Stop Condition-Street 1	StopSign
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Possible Solution			Field Measurements/Component Compliance						
Possible Solutions:			Compliance Description			Compliance Description Data			
Remove & Replace Entire Ramp.	Ram	ıp.	N/A	Ramp Length (in)	48.0	N/A	Grade	Break?	N/A
	•	Yes Ramp Width (in)		65.0	N/A	Grade	Break Slope (%)	0.0	
		No	Ramp Slope (%)	9.1	N/A	Grade	Break XSlope (%)	0.0	
			Yes	Ramp XSlope (%)	0.9				
			N/A	Flare Type LT	N/A	N/A	Flare ⁻	Гуре RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	0.0
Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare ⁻	Traversable RT?	N/A
N/A			N/A	Landing Length (in)	0.0	N/A	DWS	Provided?	N/A
			N/A	Landing Width (in)	0.0	N/A	DWS	Contrast?	N/A
			N/A	Landing Slope (%)	0.0	N/A	DWS	Length (in)	N/A
			N/A	Landing X Slope (%)	0.0	N/A	DWS	Full Width?	N/A
PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset LT (in)	N/A
R304.2.2			N/A	Shared Landing?	N/A	N/A	DWS	Offset RT (in)	N/A
			N/A	Gutter Ponding?	0.0 N/A	N/A	Gutter Slope (%)		N/A
			N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter	X Slope (%)	N/A
			N/A	Painted X Walk1?	No		Road	Slope (%)	2.4
				X Walk 1 Direction	To S		Road 2	X Slope (%)	3.3
				X Walk 1 Width (in)	N/A	l	Clear	Space?	N/A
				X Walk 1 Slope (%)	2.4	N/A	Clear	Space to XWalk (in)	N/A
				X Walk 1 X Slope (%)	3.3	N/A	Storm	Grate/Utility Hazard?	N/A
			N/A	Ramp inside XWalk1?	N/A		Storm	Grate/Utility Type	
			N/A	Any Obstructions?	N/A				N/A
Total Cost:	\$	1600.00		Obstruction Type		Yes	Surfac	e Condition? (G/P)	Good
					N/A	N/A	Curb S	Slope (%)	4.7





