## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13304 Main S	n ID: 13304 Main Street: GOLF_COURSE_LN		eet:	OLD_STEELE_CREE	Location:	S			
ADA ID: BE57E93ECD97 Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance: No					o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:	C	Compliance Description			Data Compliance Description			
	Remove & Replace Curb Ramp Wit Two New Directional Ramps or Equivalent.	ith N/	/ <b>A</b>	Ramp Length (in)	42.0	No	Ramp Slope (%)	10.3	
		Ye	es	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.9	
		N/	/ <b>A</b>	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		N	/ <b>A</b>	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		N	/ <b>A</b>	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N	/ <b>A</b>	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	N	/ <b>A</b>	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	N	/ <b>A</b>	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		N	/ <b>A</b>	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	10 A	N	/ <b>A</b>	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		N	/ <b>A</b>	Shared Landing?	N/A				
	PROW/ADA:	N	/ <b>A</b>	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.2.2, R304.5.3	N/	/ <b>A</b>	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		N	/ <b>A</b>	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
A A A A A A A A A A A A A A A A A A A				X Walk 1 Direction	To NE		X Walk 2 Direction	To W	
		N	/ <b>A</b>	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name GOLF COURSE LM	 			X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	5.4	
Stop Condition-Street 2 StopSign	1			X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	1.6	
Street 2 Name OLD STEELE CREEK R		N	/ <b>A</b>	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 None				Road Slope (%)	3.3	N/A	Clear Space?	N/A	
				Road X Slope (%)	4.7	N/A	Clear Space to XWalk (in)	N/A	
		N	/ <b>A</b>	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A	

Yes Surface Condition? (G/P)

Good

