

## **Access Compliance Report** Public Rights-of-Way (Curb Ramps)



Intersection ID: 14546	Main Street: GREENWOOD_CLIFF				Cross Street: HARDING_PL				Location: S		
ADA ID: BE757EC978C4	Ramp Type: Combination1				Initial Pass/Fail: Fail Overall Complian			ice: No Severity Score: 37.5		37.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	and the second second	Possible Solutions:			Compliance Description		Data	Comp	liance Description	Data	
		Remove & Replace	Entire Ran	np.	N/A	Ramp Length LT (in)	48.0	N/A	Ramp Length RT (in)	49.0	
	and the	•		•	Yes	Ramp Width LT (in)	59.1	Yes	Ramp Width RT (in)	59.0	
					Yes	Ramp Slope LT (%)	0.5	No	Ramp Slope RT (%)	10.9	
	June -				No	Ramp XSlope LT (%)	3.7	No	Ramp XSlope RT (%)	4.7	
	Sale Part Inter				N/A	Ramp Length (in)	27.0	Yes	Ramp Slope (%)	7.0	
	1 1				Yes	Ramp Width (in)	60.0	No	Ramp XSlope (%)	7.3	
K		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
E B		LT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	MAL . A				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	a state				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
11 201	1 Chart	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
A Contraction		Not Found, R304.5.3	3, R304.3.2		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	. 1. 1.	,			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
					N/A	Shared Landing?	N/A				
191 4 111 4 191					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	HARDING PL				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	5.4		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	8.7		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
								N/A	Any Obstruction?	N/A	
				21 STER	A	Versie			Obstruction Type		
						J YE				N/A	
			-4.50	-	17	. Constant		N/A	Storm Grate/Utility Hazard?	N/A	
				84		- Hereit			Storm Grate/Utility Type	10/2	

N/A Surface Condition? (G/P) Yes Good Curb Slope (%) 9.1





